

ERRATA

AWS A2.1:1998, American Welding Society Welding Symbol Chart

The following Errata have been identified and incorporated into the current reprint of this document.

Page 1 -- Under Location of Elements of a Welding Symbol, correct spelling of “Menber” in connecting reference.....callout to read “Member”.

Page 2 -- Under Square-Groove Welding Symbol, correct “3/16” to read “(3/16)”.

Page 2 -- Under Symbol with Backgouging, correct “Back Gouge” to read “Backing Weld Backgouge”.

Page 2 – Under Flush Contour Symbol, add a tail and “Back Weld“ in the tail.